


1

USE A FLATHEAD SCREWDRIVER TO
POP OUT THE 4 PINS



2

CAREFULLY REMOVE THE BLADE



3

WASH BLADE AND HANDLE WITH
SOAP AND FRESH WATER TO
REMOVE DEBRIS AND RESIDUE.
DRY COMPLETELY



4

SPRAY WITH SILICONE FOR ADDED
PROTECTION AGAINST CORROSION